# SPEC SHEET + MEASUREMENTS

## Bulwark® EXCEL FR® ComforTouch® Dress Uniform Shirt. SLU2

**Product photo**



Arc Rating ATPV 8.6 calories/cm$^2$

FABRIC Flame-resistant EXCEL FR® ComforTouch® 7-ounce, 88/12 cotton/nylon

FEATURES Industrial laundry friendly. Banded, topstitched, button-down collar. Placket front with button closure. Tailored sleeve plackets. Topstitched cuffs with button closures.

STANDARDS This flame-resistant garment meets the requirements of NFPA 2112, Standard on Flame-Resistant Garments for Protection of Industrial Personnel Against Flash Fire 2018 Edition; EN ISO 11612:2008, Protective Clothing Against Heat and Flame; EN 340:2003, Protective Clothing--General Requirements; and IEC 61482-2:2009, Live Working--Protective Clothing Against the Thermal Hazards of an Electric Arc.

**CARE INSTRUCTIONS**

Machine wash inside out with like colors. No bleach. No starch or fabric softeners. No products containing hydrogen peroxide. Tumble dry. Failure to launder properly could affect the flame resistance.

**Sketches**



front



back

## PRODUCT MEASUREMENTS

| | S | M | L | XL | 2XL | 3XL | 4XL |
|---|---|---|---|---|---|---|---|
| Body Length at Back | 33 1/4 | 33 5/8 | 34 | 34 3/8 | 34 3/4 | 35 1/8 | 35 1/2 |
| Chest | 47 3/8 | 51 3/8 | 55 3/8 | 59 3/8 | 63 3/8 | 67 3/8 | 71 3/8 |
| Sleeve Length from Center Back | 34 1/8 | 34 5/8 | 35 1/8 | 35 5/8 | 36 1/8 | 36 1/8 | 36 1/8 |

**Body Length at Back:** Measured from high point shoulder to finished hem at back.

**Chest:** Measured across the chest one inch below armhole when laid flat.

**Sleeve Length from Center Back:** Measure from Center Back neck to shoulder point to sleeve hem.

## SIZE CHARTS

| | S | M | L | XL | 2XL | 3XL |
|---|---|---|---|---|---|---|
| Arm | 33 | 33 1/2 | 34 | 34 1/2 | 35 | 35 |
| Chest | 32 1/2-36 | 36 1/2-40 | 40 1/2-44 | 44 1/2-48 | 48 1/2-52 | 52 1/2-56 |
| Neck | 13 5/8-14 1/2 | 14 5/8-15 1/2 | 15 5/8-16 1/2 | 16 5/8-17 1/2 | 17 5/8-18 1/2 | 18 5/8-19 1/2 |

## HOW TO MEASURE




**Neck** Measure around the fullest part of the neck at the base. **Chest Width** Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal. **Arm** Place hand on hip. Start at the center of the back of the neck and measure across the shoulder, to the elbow, and then down to the wrist.

## COLORS

Khaki
PMS 7503C

Light Blue
PMS 346C

Navy
PMS 433C

Silver Grey