

SPEC SHEET + MEASUREMENTS

Brooks Brothers

Brooks Brothers® Wrinkle-Free Stretch Nailhead Shirt.

BB18002

Product photo



Balancing a professional look with business-casual style, our nailhead dress shirt features a subtle two-color pattern and a soft hand. A premium wrinkle-free treatment process keeps it looking sharp and stylish all day.

- 4-ounce, 95/5 cotton/spandex fine yarn count
- Button-down collar
- Left chest pocket
- Taped seams
- Dyed-to-match buttons with Brooks Brothers logo
- Rounded, adjustable cuffs
- Rental-friendly

CARE INSTRUCTIONS

Machine Wash Warm With Like Colors. Only Non Chlorine Bleach, If Needed. Tumble Dry Low. Remove Promptly And Hang. Warm Iron, If Needed.

Sketches



front



back

SPEC SHEET + MEASUREMENTS



Brooks Brothers® Wrinkle-Free Stretch Nailhead Shirt. BB18002

PRODUCT MEASUREMENTS

	XS	S	M	L	XL	2XL	3XL	4XL
Chest	19 1/2	21	22 1/2	24	26	28	30 1/2	33 1/2
Body Length at Back	29 1/2	30	30 1/2	31	31 1/2	32	32 1/2	33
Sleeve Length from Center Back	33 3/4	34 1/2	35 1/4	36	36 3/4	37 1/2	38 1/4	39
Neck Circumference	15 1/2	16	16 3/4	17 1/2	18 1/4	19	19 7/8	20 7/8
Pocket Height	4 3/4	4 3/4	5	5	5	5	5	5 1/4
Pocket Width	4 3/8	4 3/8	4 5/8	4 5/8	4 5/8	4 5/8	4 5/8	4 7/8

Chest: Measured across the chest one inch below armhole when laid flat.

Body Length at Back: Measured from high point shoulder to finished hem at back.

Sleeve Length from Center Back: Measure from Center Back neck to shoulder point to sleeve hem.

Neck Circumference: Measure from center of button to end of buttonhole along the center of the collar stand.

Pocket Height: Measure from top to bottom at center.

Pocket Width: Measure from side to side at top edge.

SPEC SHEET + MEASUREMENTS




Brooks Brothers® Wrinkle-Free Stretch Nailhead Shirt. BB18002

SIZE CHARTS

	XS	S	M	L	XL	2XL	3XL	4XL
Chest	32-34	35-37	38-40	41-43	44-47	48-51	52-56	57-61
Neck	14 1/2 - 15	15 - 15 1/2	15 1/2 - 16	16 - 16 1/2	16 1/2 - 17	17 - 17 1/2	17 1/2 - 18	18 - 18 1/2
Arm	30 1/2	32	34	35	36 1/2	37 1/2	38 1/2	39 1/2

HOW TO MEASURE



Neck Measure around the fullest part of the neck at the base.

Chest Width Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal. **Arm** Place hand on hip. Start at the center of the back of the neck and measure across the shoulder, to the elbow, and then down to the wrist.

COLORS



Club Green



Cobalt Blue



Deep Black
PMS BLACK
C



Navy Blazer/
Vintage Port



Newport Blue
PMS 7681C



White